

Yadao

Product Name	
Material	
Size	80 * 60 mm (Minimum Order Quantity: 1000 pieces)
Color	Black, White, Grey, Customized, bidge... (Minimum Order Quantity: 1000 pieces)
Quantity	3000 pieces
Lead Time	
Packaging	Standard Packaging
	Customized Packaging: 7 days
	Customized Packaging: Minimum Order Quantity 1000 pieces
MOQ	20-25 pieces (Minimum Order Quantity: 1000 pieces)
OEM / ODM	Yes
Payment Terms	Trade Assurance (Minimum Order Quantity)

PS: Minimum Order Quantity: 1000 pieces / Customized Packaging: 7 days

Minimum Order Quantity: 1000 pieces (Minimum Order Quantity: 1000 pieces)



XXXXXXXXXXXXXXXXXXXXXXXXXX:



Jewelry paper bag

□□□□□ □□□□□



Yadao Division

Shenzhen Yadao Packaging Design Co. , Ltd.

Shenzhen Yadao Packaging Design Co. , Ltd. 2546

()... /)



中国制造网 认证供应商
AUDITED SUPPLIER

Presented To

Shenzhen Yadao Packaging Design Co., Ltd.

深圳市雅岛包装设计有限公司

<http://cnbzshow.en.made-in-china.com>

In Recognition of Your Site Existence & Business Operations

Audited by SGS-CSTC on 2012-04-01. Validity is from 2012-04-01 to 2013-03-31.

Audit Report Serial No.: QIP-ASI122374

Made-in-China.com
中国制造网

SGS

□□□□□□□□□□□□□□





01.Cutting



02.Sewing



03.Stitching



04.Printing



05.Trimming



06.Inspection



01. How do you prepare the fabric before cutting?

1. Pre-pressing / Pre-shrinking / Ironing
2. Pre-washing / Pre-dyeing / Pre-bleaching / Pre-softening / Pre-finish
3. Pre-finishing / Pre-dyeing / Pre-bleaching / Pre-softening / Pre-finish
4. Pre-washing / Pre-dyeing

02. How do you control the quality of the fabric during sewing?

Ans. Regularly inspect the fabric for any defects or damage. Use a gauge to check the fabric's dimensions. 2546 cm width fabric 10 cm

03. How do you control the quality of the fabric during printing?

Ans. Use a color calibration chart to ensure accurate color reproduction. Use a resolution test chart to ensure sharp printing. Use a color management system to control the printing process.

Q4. How do you control the quality of the fabric during inspection?

Ans. Use a color calibration chart to ensure accurate color reproduction. Use a resolution test chart to ensure sharp printing. Use a color management system to control the printing process.

